



Campbell M. Gilmour
Director

DEPARTMENT OF TRANSPORTATION AND DEVELOPMENT

SUNNYBROOK SERVICE CENTER

9101 SE SUNNYBROOK BLVD. | CLACKAMAS, OR 97015

June 9, 2008

PCR, Inc.
PO Box 630
Beavercreek, OR 97004

SUBJ: Gronlund Road Slide Repair
RM-06-15
Letter of Recommendation

This letter is a Letter of Recommendation to PCR, Inc based on our work together on the Gronlund Road Slide Repair.

As with many of the landslide repair projects I have worked on, many things change during construction. On this project we encountered some material that had to be removed which required some small changes to the benching of the underlying soils. While this isn't much of a change, the result was a total redesign of the underlying drainage system.

PCR continued to "pursue unto completion, in a workman like manner" the task at hand. This even extended to working with the neighboring landowner.

It is this type of partnering that allows me to write this Letter of Recommendation.

If I can be of any further assistance, please contact me at 503-353-4674.

William A. Garly - Inspection Supervisor
Construction & Development Services Section